Print-Sloop 2-22-73

YACHT AMERICA



H-361-380

© 1969 BY REVELL INC., VENICE, CALIF. 90291

★ ★ BEFORE YOU BEGIN ★ ★ ★

LITHO IN U.S.A.

GET YOUR TOOLS READY:



TO DETACH AND TRIM PARTS FILE TO REMOVE







CEMENT USE TOOTHPICK PAINT BRUSH OR PIN TO APPLY IT







DO NOT DETACH PARTS UNTIL YOU ARE READY TO USE THEM! PARTS ARE NUMBERED TO HELP YOU FIND THEM. LOOK FOR THE NUMBER ON TAB NEXT TO PART OR ON PART ITSELF.


FIRST, FIT PARTS TOGETHER and TRIM EXCESS PLASTIC. Use a toothpick, pin or small paint brush to apply cement. APPLY CEMENT SPARINGLY. Too much cement will damage your model.


NOTE: In the illustrations some of the details on the parts have been OMITTED FOR CLARITY.

If you so desire, your model of the America may be used as a floating model. Carefully follow the directions for ballasting in Step 3 of the Assembly instructions. Be sure you have a water IF YOU WISH TO PAINT YOUR MODEL — See PAINTING on all steps for color suggestions.

- Paint small parts before detaching from runner.
- Start with the lighter colors.
- Scrape off paint where cement is to be applied. Cement will not work on paint.


tight seam between hull halves and that ballast weight is firmly secured to hull to prevent its shifting after deck is installed.






hull has completely set.


2. Approximately 15 OUNCES of WEIGHT are REQUIRED to properly ballast the hull. This should be a combination of fishing weights or B-B shot and oil base modeling clay. The WEIGHT should be DISTRIBUTED along the LENGTH of the HULL and as LOW as possible, and equally distributed from side to side. With ballast weight properly distributed, the water line should match the hull line from front to rear as well as from side to side. Check by floating hull and if properly weighted, press clay firmly to hull to hold ballast in position.



- 9. WINDLASS
- 10. DECK
- 11. FORWARD SKYLIGHT
- 12. FORWARD HATCH 13. CAPSTAN TOP 14. CAPSTAN
- 15. GALLEY STACK BLACK
- Cement the WINDLASS (9) to the DECK (10).
 Cement the FORWARD SKYLIGHT (11) and FORWARD HATCH (12) to the DECK.
- Cement the CAPSTAN TOP (13) to the CAPSTAN (14). Cement assembly to the
- 4. Cement the GALLEY STACK (15) to the DECK.


PAGE 2






- 16. EYEBOLTS (8 Parts)
 17. SINGLE BLOCKS (8 Parts)
- CLEATS (4 Parts)
- 18. IRON HORSE

- 1. Cement eight EYEBOLTS (16) to DECK then tie eight SINGLE BLOCKS (17) to the EYEBOLTS.
- 2. Cement four CLEATS (8) to the DECK.
- 3. Cement the IRON HORSE (18) to REAR of DECK.




- REAR SKYLIGHT
- COMPANIONWAY LEFT SIDE
- COMPANIONWAY RIGHT SIDE
- 22. COMPANIONWAY FRONT
- COMPANIONWAY BACK
- COMPANIONWAY ROOF
- 1. Cement the REAR SKYLIGHT (19) to DECK.
- Assemble the COMPANIONWAY to the DECK by cementing the LEFT (20) and RIGHT (21) SIDES to the DECK. Then the FRONT (22) and REAR (23) to the DECK and SIDES. Then cement the COMPANIONWAY ROOF (24) to the SIDE WALLS.



- 25. 26. 27. TILLER
- COCKPIT
- STAND NAME PLATE (2 Parts)
- STAND REAR

- - 2. Cement TILLER (25) to RUDDER POST.
- 3. Cement COCKPIT (26) to DECK.
- Assemble SHIP'S STAND by cementing the two NAME PLATES (27) to the FRONT (28) and REAR (29) STAND SECTIONS.
- DO NOT CEMENT stand to the hull if you are building a floating model. For a static model cementing is optional.



- BOWSPRIT RIGHT HALF
- 31.
- 16. 7.
- BOWSPRIT LEFT HALF EYEBOLTS (4 Parts) MOORING KEVELS (2 Parts)
- CLEATS (10 Parts)
- ANCHOR DAVITS (2 Parts) 33. BULLEYES (2 Parts)
- 34.
- FOREMAST DEADEYES RIGHT FOREMAST DEADEYES LEFT 35.
- MAINMAST DEADEYES RIGHT
- 37. MAINMAST DEADEYES LEFT

- Cement the BOWSPRIT RIGHT HALF (30) to the LEFT HALF (31).
- 2. Cement two EYEBOLTS (16) and two CLEATS (8) to the BOWSPRIT.
- Cement BOWSPRIT to DECK and HULL.
- 4. Cement two MOORING KEVELS (7) and eight CLEATS (8) to INSIDE of HULL.
- 5. Cement two ANCHOR DAVITS (32) to DECK.

- Cement two ANCHOR DAYITS (32) to DECK.
 Tie two BULL EYES (33) to EYEBOLTS (16) then cement to SIDES of HULL.
 Cement RIGHT (34) and LEFT (35) FOREMAST DEADEYES to sides of HULL.
 Cement MAINMAST DEADEYES RIGHT (36) and LEFT (37) to sides of HULL.

